



BRIDGEPORT UPDATE 04/05/24

Ray Echlin, Construction Manager 818-889-0402 Ext 124 RayEchlin@DBuild.com

This Week DBA:

- Held Deck repair discussion Zoom with Don Newton and Claire Nelson and 2nd chair Dennis Brooks.
 - Discussed Board concerns about quality of work and conditions were presented (and acknowledged) in order to approve RCO 21.
- Received Rayco Pay 14 and reviewed for accuracy and reasonableness.
- Held onsite Construction Meeting with Rayco foreman, superintendent, project manager and waterproofing sub-contractor.
 - Walked project status, met with Don Newton to walk painting and discuss immediate response to concerns at 4643.
 - Stucco at 4643 will be closed by EOB Tuesday 4/9.
 - Discussed scheduling of labor and order of materials for scope of Change Order 14.
 - Walked walkway waterproofing scope with sub-contractor to review Life Deck spec.
- Post Shortening (continued): West side 3rd floor will be completed after railing install complete, as the bottom rail is used as cut line.
- Railings (Continued): West side 2nd floor 98%, 3rd floor 98%
 - Rescheduled to finish 4/10 including all detail work (corners, lower rail, touchups and corrections).
 - Once complete, City inspection of railing post fasteners will be requested.
 - Once passed, we can begin to install plywood sheathing and schedule waterproofing.
 - Rayco welders
- Beams:
 - West Side:
- Change Order 14 approved and received 4/4.
- Materials have been ordered; Work on Beam Q and Post R scheduled for 4/15 when carpentry crew returns.
- Painting update:
 - East: Bldg 1- 100%, Bldg 2 100%, Bldg 3 100%, Bldg 4 100%
 - Rayco "detail" crew to commence touch-ups and clean-ups as soon as final building 7 is completed. Rayco will be taking care of existing punchlist items prior to DBA punch walk.
 - Entry Doors were painted open if owner was home. Doors needing painting will be verified and appointments will be made.
 - West: Buildings 5, 6: 100% except front doors. Bldg. 7 85%. Bldg. 8 99% complete.
- Balcony Repair:
 - Change Order 14 approved and received 4/4. Work at balconies 4743,4661,4655,4637,4735,4749,4645 scheduled to begin on 4/15. Finalized schedule to be drafted and communicated.
 - Continued: Rayco will inventory PER BLDG wood railing topper to be replaced and take replacement material recycled from railing demolition.





BRIDGEPORT UPDATE 04/05/24

Ray Echlin, Construction Manager 818-889-0402 Ext 124 RayEchlin@DBuild.com

- Continued: Rayco will inventory any wrought iron metal replacement (if missing material) need to be performed at each unit and to be verified by DBA for change order.
- Waterproofing:
 - East side: plywood sheathing passed floor and nailing inspection. 100%
 - Westside Sheathing: 75%
 - Waterproofing Contractor will commence in phases once all walkways are ready and sheathing installed.
 - Walkway schedule and progress map will be communicated and posted at client site at Dbuild.com.
- City Inspections:
 - 3rd floor Railing connections pending install after beam replacement.
 - Westside beam inspection postponed until Beam Q and Post R are completed.

Next Week DBA will:

- Be onsite to for weekly construction meeting with RayCo. and to verify critical path items of beam completion, railing completion, initial paint completion, deck repairs.
- Upload Weekly Update to client site.
- Be available for questions, comments

Have a great weekend.