


BRIDGEPORT BALCONY REPAIR SCOPE



- 1.4661 verified RECOAT/OVERLAY
- 2.4655 verified RECOAT/OVERLAY
- 3.4637 verified REBUILD/ SHEATHING; inspect deck-to-wall flashing for possible replacement
- 4.4673 verified RECOAT/OVERLAY (PATCH SHEATHING AT SOFT SPOT)
- 5.4731-verified RECOAT/RESLOPE for Drainage
- 6.4735- verified REBUILD/SHEATHING; inspect deck-to-wall flashing for possible replacement
- 7.4737 verified RECOAT/OVERLAY
- 8.4743 verified RECOAT/OVERLAY (PATCH SHEATHING AT SOFT SPOT)
- 9.4751 verified RECOAT/OVERLAY
- 10.4749 verified REBUILD/SHEATHING; inspect deck-to-wall flashing for possible replacement
- 11.4741 verified RECOAT/OVERLAY